



To install the **Honeywell IS3000 Series** scanner to work with Hula POS, perform the following tasks:

1. Connect the scanner to the **S-Line** series computer using the USB port located on the left side of the terminal.
2. Use the included screws to secure the reader to the unit using a standard phillips head screwdriver.
3. Turn to page 11 in the included **QuantumE Scan Engine User's Guide**. Scan the **Enable Laser Emulation Mode** barcode, the scanner will beep 3 times.
4. Next, turn to page E12 in the included **Metrologic MetroSelect Configuration Guide**. Find and scan the barcode named **Enable "\$" Prefix ID for UPC/EAN**, the scanner will beep 3 times. Your scanner is now installed and configured to work with Hula POS.